## Chapter

# 5

## Solid Part Four – A Bracket Made by Mirroring

This chapter will cover the following to World Class standards:

- Sketch of a Solid Problem
- Draw a Series of Lines
- Finish the 2D Sketch
- Extrude a 2D Sketch
- Add Multiple Fillets
- Add Multiple Holes
- Add a Slotted Hole
- Add a Tapped Hole
- Mirror the Solid

## **Sketch of Solid Part Four**

Again we start any project by making a sketch, so we can efficiently produce a drawing. In part 4, we see a sketch of another bracket. The length of the bracket legs are 1 inch long. The thickness of the material is 0.125. There are four 0.125 rounds or fillets and four 0.201 diameter holes on the feet of the bracket. At the top of the bracket, we have a 0.5 by 1.0 slotted hole and two 6-32 UNC tapped holes.



#### **Figure 5.1 – Problem Four Sketch**

In the fourth problem, we will practice techniques that we learned in the previous part sketches and add some new experiences such as slotted holes, tapped holes and mirrored solids. We will continue to add holes and fillets. We will still use multiple sketches and extrusion techniques to create the solid part.

In this project, we will only draw half of the bracket and then when we are done with graphically describing all of the features, we will mirror the solid to make the entire bracket.

## **Starting a 3D Part Drawing Sketch**

When we open the	e AutoCAD Inver	ntor application, we will	select New from the	e menu.	
Get Sarted Get Sarted New (Ctri=N) Launch Ro Browser *	Autodesk Inventor Professional 2012	Type is leyword or phrase Engineers Wild Customer Rule ORIS Help Involvement Community	11 🔨 🏦 🛓 Sign In		
	Autodesk'	<b>Inventor</b> <sup>®</sup> Professional			Autodesk

### **Figure 5.2 – AutoCAD Inventor Professional 2012**

A New File window will appear and there are four tabs on this dialogue box. They are Default, English, Metric and Mold design. For this drawing, we will select the English tab and the Standard (in) ipt template. We will press the OK button to continue.



Figure 5.3 – Starting the drawing using the **Standard IPT template** 

To turn off the grid if it is on the new drawing, we will go to the Tools tab on the Ribbon and choose Applications Options.



### **Figure 5.4 – Starting the drawing using the Standard IPT template**

In the Applications Options dialogue box, we will turn off the Grid Lines.

For this chapter, we picked the Colors tab on the Applications Options and we select 1 background color and Presentation for the Color Scheme list. Having the grid and color on the drawing sketch background has no effect on the drawing, but is the designer's personal preference.

General	Save	File	Colors	Display	Hardware	e Prompts	Assembly
Content	Center	Drawing	Ske	tch p	Part	iFeature	Notebook
D Sketch							
Constra	aint placem	ent priority		Disp	olay		
Par	allel and pe	rpendicular			Grid lines		
O Hor	rizontal and	vertical			Minor grid line	as	
0		P			Axes		
Overco	instrained d	limensions			Coordinate s	ystem indicator	
O App	oly driven d	imension		[FT]	Display coinci	ident constraints	on
Wa	rn of overc	onstrained co	Indition		creation Co	ostraint and DOI	F
					1 isyr	mbol scale	
Spline f	fit method			Hea	ads-Up Displa	у	
<ul> <li>Standard</li> </ul>				V	Enable Heads	s-Up Display (HU	D)
O Aut	OCAD				Setting	IS.	
Mini	imum Energ	w - Default Te	ansion				
0	main energ	y Derduit re	1 Sion				
Ų	10 10 10 1		1.0.0				
0			100				
Snap	to grid						
🔲 Edit d	limension wl	hen created					
Autop	project edge	es during curv	e creation				
Autop	project edge	es for sketch	creation an	nd edit			
Look #	at sketch pl	lane on sketch	n creation				
V Autor	project part	origin on ske	tch create				
V Point	alignment						
D Sketch							
Auto-	bend with 3	3D line creatio	'n				

**Figure 5.5 – Application Options Window** 

## **Drawing a Series of Lines**

The entity we will learn to draw in Inventor is a Line. We right click on the drawing and we can see Line in the center top of the menu.

To draw a line, we right click on the drawing and we can see Line, Center Point Circle, Two Point Rectangle and many more choices. We pick Line and we will single click on the center portion of the graphical display and then we can pull the line in any direction.



Line 🔽

#### **Figure 5.6 – Graphical Display Menu**

To draw a series of lines to create a profile, we begin by picking a point on the lower left portion of the graphical display and then we pull the line to the right. We keep the cursor directly to the right and the application will report 0.00 degrees in the horizontal. We will input 1.125 in the measurement textbox and press the Enter key.

Next, we draw a line perpendicularly upward at 90 degrees. We will input 1.875 in the measurement textbox and press the Enter key.









Then we draw a line perpendicularly to the right at 90 degrees. We will input 0.75 in the measurement textbox and press the Enter key.



**Figure 5.9 – Third Line Segment** 

We then draw a line perpendicularly upward at 90 degrees. We will input 0.125 in the measurement textbox and press the Enter key.



**Figure 5.10 – Fourth Line Segment** 



**Figure 5.11 – Fifth Line Segment** 

We then draw a line perpendicularly to the left at 90 degrees. We will input 0.75 in the measurement textbox and press the Enter key. We then draw a line perpendicularly downward at 90 degrees. We will input 1.875 in the measurement textbox and press the Enter key.



**Figure 5.12 – Close the Profile** 

We then draw a line perpendicularly to the left at 90 degrees. We will input 1.0 in the measurement textbox and press the Enter key.



Figure 5.13 – Diagonal Line

For the last segment, we will want to close the profile, so we right click on the graphical display and we select Close from the menu. The bracket will appear as shown in Figure 5.14.



**Figure 5.14 – Diagonal Line** 



**Figure 5.15 – Profile with Dimension Showing** 

\* World Class CAD Challenge 61-09 \* - Close this drawing file. Create a New file and draw the profile of eight lines. Complete the task in less than 5 minutes. Continue this drill four times, each time completing the drawing under 5 minutes to maintain your World **Class ranking.** 

\* World Class CAD Challenge \* - Report your best times to World Class CAD at www.worldclasscad.com to obtain your world class ranking.

## Finish 2D Sketch of Solid Part One

Before we extrude the sketch, we need to right click on the graphical display and on the menu; we choose the Finish 2D Sketch button.





Figure 5.16– Finish 2D Sketch

**Extruding a 2D Sketch** 

Now that we have a finished sketch, we need to extrude the part. We can go ahead and pick the Extrude button on the Model tab of the Invertor ribbon. The Extrude window will appear on the display.

On the Extrude window, we can either output a solid or surface. The differences between the two are that the first is like a hard piece of aluminum and the second choice is similar to a box. We will pick the Solid output on the left. Next, our part will be made from finished aluminum, so we will change the Extents distance from 1.0 to 1.5.

We select the profile area and when it turns red, we click again to extrude the solid.



**Figure 5.17 – The Extrude Window** 

### **Drawing Multiple Fillets**

The next feature we will add to our bracket is the four fillets. We choose the Fillet button on the Inventor ribbon and the Fillet window will appear on the graphical display.

We set the fillet radius to 0.125. When we select the straight edged corner, the pointed edge will change to a 0.125 inch rounded corner.



**Figure 5.18 – First Fillet** 





We should select the other three straight edges and the pointed edges will change to a 0.5 inch rounded corners.

To make the placements permanent, we press the OK button.





After closing the Fillet window, we are ready to add the clearance holes in the base of the bracket.



**Figure 5.20 – Finished Fillet** 

## **Drawing Multiple Holes**

The next entity we will learn to draw in Inventor is a Hole. We choose the Hole button on the Inventor ribbon and the Hole window will appear on the graphical display.



We begin the process of adding a hole by making a new sketch.





We then choose the plane for the new sketch, so we pick the surface as shown in Figure 5.22.









**Figure 5.23 – Select Center Point** 

We place the cursor over the top yellow line of the plane to find the midpoint and we place a point towards the top of the plane and another directly below it. We will add dimensions to locate the centers precisely.



**Figure 5.24 – Select the Two Centers** 

We choose Dimension on the Inventor ribbon and we pick the top left corner of the plane and the center of the top center point. The dimension is 0.500. We again choose Dimension on the Inventor ribbon and we pick the top left corner of the plane on the center of the top center point. We will edit the dimension and input 0.25.



**Figure 5.25 – Dimension the Top Center** 

For the third time, we select Dimension on the Inventor ribbon and we pick the center of the top center point and the center of the bottom center point. We will edit the dimension and input 1.0.



**Figure 5.26 – Dimension the Bottom Center** 

Before we extrude the sketch, we need to right click on the graphical display and on the menu; we choose the Finish 2D Sketch button.



Figure 5.27 – Finish the 2D Sketch

We then select the Hole button on the Inventor ribbon and the Hole window will appear on the graphical display. We are making a 0.201 through hole, so we change the diameter textbox from 0.25 to 0.201. The two hole placements appear automatically and we press the OK button to retain the feature.



Figure 5.28 – Add Holes to the Centers

## **Drawing a Slotted Hole**

We begin the process of adding a hole by making a new sketch.



**Figure 5.29 – Another New Sketch** 

We then choose the plane for the new sketch, so we pick the surface as shown in Figure 5.30.



**Figure 5.30 – Select the Plane** 

We want to draw a rectangle on the plane, so we right click on the drawing and we can see Create Line, Center Point Circle, Two Point Rectangle and many more choices. We pick Two Point Rectangle and we will single click on the yellow right edge of the plane and another point on the middle of the plane.

This any sized rectangle on the plane has two dimensions. The horizontal measurement is highlighted and we can type 0.25. We press the tab on the keyboard to switch to the vertical dimension and we input 1.0.

We choose Dimension on the Inventor ribbon and we pick the top right corner of the plane and the top right corner of the rectangle. The dimension is 0.25.

Before we extrude the sketch, we need to right click on the graphical display and on the menu; we choose the Finish 2D Sketch button. 1.0 P 0.250 in 1

### Figure 5.31 – Add a Rectangle



Figure 5.32 – Add a Dimension





23 Extrude Shape More Profile • Distance Solids ₽ 1 in P. Ð Output 69 2 V 60 OK Cancel (**→**▼ 1in Profile 🔻



Now that we have a finished sketch, we need to extrude the slot. We can go ahead and pick the Extrude button on the Model tab of the Invertor ribbon. The Extrude window will appear on the display. Then we will click on the slot and it will become highlighted in red. Click on the direction icon so that the new solid goes down into the bracket. Click on the red area again and a rectangular slot will appear in the top of the bracket.



The next feature we will add to our slot is two fillets. We choose the Fillet button on the

Inventor ribbon and the Fillet window will appear on the graphical display. We set the fillet radius to 0.25. When we select

the straight edged corner inside the rectangular slot, the pointed edge will change to a 0.25 inch rounded corner.

Figure 5.35 – Extrude the Slot

2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Edges Radus De 1 Selected .25 Click to add	select mode  e trige base base base base base base base bas
		Festire     Solds     Ar Filets     A Rounds
2	l that ox can	el Acoly >>

Figure 5.36 – Add Two Fillets

## **Drawing a Tapped Hole**

We begin the process of adding a hole by making a new sketch.



Figure 5.37 – Start a New 2D Sketch

We then choose the plane for the new sketch, so we pick the surface as shown in Figure 5.38.



**Figure 5.38 – Select the Plane** 

Now, we will select Point on the Sketch tab of the Inventor ribbon. Then we place the cursor over the left yellow line of the plane to find the midpoint and we place a point towards the middle of the plane. We will add dimensions to locate the centers precisely.



Figure 5.39– Add a Center Point



**Figure 5.40 – Dimension the Center Point** 







Figure 5.42 – Add a Tapped Hole

We choose Dimension on the Inventor ribbon and we pick the top right corner of the plane and the center of the center point. The dimension is 0.4375, so we will edit the dimension and input 0.4375.

Before we extrude the sketch, we need to right click on the graphical display and on the menu; we choose the Finish 2D Sketch button.

We then select the Hole button on the Inventor ribbon and the Hole window will appear on the graphical display. We are making a 6-32 tapped hole, so we choose the tapped hole icon. We pick ANSI Unified Screw Threads, 0.138 (#6) for the size, 2B for the class and 6-32 UNC for the designation. The hole that automatically appeared will appear tapped and we press the OK button to retain the feature.

## Mirror a Solid

The next function we will learn to draw in Inventor is mirror. We choose the Mirror button on the Inventor ribbon and the Mirror window will appear on the graphical display.

We select the Solid icon and then the Mirror Plane icon. We pick the plane as shown in figure 5.43.



**Figure 5.43 – Select the Mirror Plane** 

The other half of the solid will appear as a wireframe. We press the OK button to make the complete bracket.

We can change the view to see the hidden lines, so we go to View on the Inventor ribbon and we choose Visual Style and pick Shaded with Hidden Edges. The drawing appears as shown in figure



Figure 5.44 – The Mirrored Solid



Figure 5.45 – The Finished Solid



Save the solid bracket and we will make a new one in the next chapter.

\* World Class CAD Challenge 61-10 \* - Close this drawing file. Create a New file and draw the profile of eight lines. Add two holes on the bottom plane. Add a slotted hole and a tapped hole on the top plane. Mirror the solid. Complete the task in less than 10 minutes. Continue this drill four times, each time completing the drawing under 10 minutes to maintain your World Class ranking.

\* World Class CAD Challenge \* - Report your best times to World Class CAD at www.worldclasscad.com to obtain your world class ranking.