



CURVE LENGTH

THE CURVED LENGTH IS REQUIRED WHEN A RADIUS IS SHOWN ON A PART AND THE PART WILL BE REQUIRED TO BE MADE IN THE FLAT, AND THEN RADIUSED.



LEFT CLICK ON EDGE

RESULTS

EDGE LENGTH = 49.8911